

Food Quality Lab

3375 Koapaka Street, G314
Honolulu, HI 96819
Phone: 808-839-9444, Fax: 808-839-9744

Customer name and mailing address

Jack and Jill

Down the Hill
Tumble, Rhyme, 12345
Attn: Jill
Project Name: Sample Project
PO No: 8888

Project Manager

Date/time received at lab

Received: 11/10/2009 @ 10:30 AM

Completed: 11/12/2009 @ 3:30 PM

Project Number: 091110-2457-001

Temperature: 25.0 °C

Client Project No: 12345

Sampler name

LAB REPORT

Temperature taken at lab at time of receipt

Date/Time sample taken

Sample ID: 091110-2457-001-01

Pail of Water
Location: Up the Hill

Sample Matrix

Sampled: 11/9/2009 @ 9:30 AM

Sampler: Jack

Analysis	Results	Units	MDL	Test Method	Analized	By
Fecal Coliform (MF)	<1	MF/100ml	1	SMWW 21 9222B	11/10/2009 11:30 AM	BU
Settleable solids	<0.1	mL/L	0.1	SM 2540FA	11/10/2009 11:30 AM	BU

Sample Description

assigned by lab

Method Detection Limit

Date/Time of analysis

Analyst

Approved By: _____

Thursday, November 12, 2009